
	CLASSIFICATIONSTOP TO
COUNTRY.	Germany (Soviet Zone) REPORT NO.
TOPIC	Beurnppin Airfield
	NW6
EVALUATIO	N/60
	CONTENT Prior to 13 March 1951
32.0	
DATE OBTA	
REFERENC	ES
PAGES	2 ENCLOSURES (No. & TYPE)
REMARKS.	
	FREE PROPERTY CAND CO.
,	DO NOT CIRCULATE
,	7
1.	Prior to 13 March 1951, Colonel Postinkov, (fnu), Lieutenant Colonel
٠.,	Zukhornikov, (fnu), and Lieutenant Colonel Karnatovski, (fnu), visited
	Mouruppin airfield (N 53/2 49). The officers were assigned to the
	Condition which the condition of the con
*	Soviet construction offices located in Karlshorst (1 53/2 94) and Werder
	Soviet construction offices located in Karlshorst (N 53/Z 94) and Werder (N 53/Z 63).  The construction staff in Neuruppin including Lieutenant Colonel Vinceradov.
	Soviet construction offices located in Karlshorst (N 53/Z 94) and Werder (N 53/Z 63).  The construction staff in Meuruppin including Lieutenant Colonel Vinogradov, (fnu), and technical officer Captain Makarov. (fnu), were subordinate to
	Soviet construction offices located in Karlshorst (N 53/Z 94) and Werder (N 53/Z 63).  The construction staff in Neuruppin including Lieutenant Colonel Vinceradov.
2.	Soviet construction offices located in Karlshorst (N 53/Z 94) and Werder (N 53/Z 63).  The construction staff in Neuruppin including Lieutenant Colonel Vinogradov, (fnu), and technical officer Captain Makarov, (fnu), were subordinate to Colonel Postnikov. The officers of the construction staff were yellow-bordered
2.	Soviet construction offices located in Karlshorst (N 53/Z 94) and Werder (N 53/Z 63).  The construction staff in Meuruppin including Lieutenant Colonel Vinogradov, (fnu), and technical officer Captain Makarov, (fnu), were subordinate to Colonel Postnikov. The officers of the construction staff were yellow-bordered red epaulets and red ribbons on their caps. (1)  The following is a description of the jet fighters at the field:
2.	Soviet construction offices located in Karlshorst (N 53/Z 94) and Werder (N 53/Z 63).  The construction staff in Neuruppin including Lieutenant Colonel Vinogradov, (fnu), and technical officer Captain Makarov, (fnu), were subordinate to Colonel Postnikov. The officers of the construction staff were yellow-bordered red epaulets and red ribbons on their caps. (1)  The following is a description of the jet fighters at the field:  Cockpit canopy slids back; nosewheel extends rearward and not forward as previously reported; two camons one above the other on left side of nose
2.	Soviet construction offices located in Karlshorst (N 53/Z 94) and Werder (N 53/Z 63).  The construction staff in Neuruppin including Lieutenant Colonel Vinogradov, (fnu), and technical officer Captain Makarov, (fnu), were subordinate to Colonel Postnikov. The officers of the construction staff were yellow-bordered red epaulets and red ribbons on their caps. (1)  The following is a description of the jet fighters at the field:  Cockpit canopy slids back; nesewheel extends rearward and not forward as previously reported; two cannons one above the other on left side of nose when observed from the front, two machine guns on right side, one a little
2.	Soviet construction offices located in Karlshorst (N 53/Z 94) and Werder (N 53/Z 63).  The construction staff in Neuruppin including Lieutenant Colonel Vinogradov, (fnu), and technical officer Captain Makarov, (fnu), were subordinate to Colonel Postnikov. The officers of the construction staff were yellow-bordered red epaulets and red ribbons on their caps. (1)  The following is a description of the jet fighters at the field:  Cockpit canopy slide back; nosewheel extends rearward and not forward as previously reported; two cannons one above the other on left side of nose when observed from the front, two machine guns on right side, one a little to the rear; The brocchi piece of weapons with live ammunition is marked by red flags when aircraft are parked. Planes that are refueled are fitted with
2.	Soviet construction offices located in Karlshorst (N 53/Z 94) and Werder (N 53/Z 63).  The construction staff in Neuruppin including Lieutenant Colonel Vinogradov, (fnu), and technical officer Captain Makarov, (fnu), were subordinate to Colonel Postnikov. The officers of the construction staff were yellow-bordered red epaulets and red ribbons on their caps. (1)  The following is a description of the jet fighters at the field:  Cockpit canopy slids back; nesewheel extends rearward and not forward as previously reported; two cannons one above the other on left side of nose when observed from the front, two machine guns on right side, one a little
2.	Soviet construction offices located in Karlshorst (N 53/Z 94) and Werder (N 53/Z 63).  The construction staff in Neuruppin including Lieutenant Colonel Vinogradov, (fnu), and technical officer Captain Makarov, (fnu), were subordinate to Colonel Postnikov. The officers of the construction staff were yellow-bordered red epaulets and red ribbons on their caps. (1)  The following is a description of the jet fighters at the field:  Cockpit canopy slide back; nosewheel extends rearward and not forward as previously reported; two cannons one above the other on left side of nose when observed from the front, two machine guns on right side, one a little to the rear; The brocchi piece of weapons with live ammunition is marked by red flags when aircraft are parked. Planes that are refueled are fitted with
2.	Soviet construction offices located in Karlshorst (N 53/Z 94) and Werder (N 53/Z 63).  The construction staff in Neuruppin including Lieutenant Colonel Vinogradov, (fnu), and technical officer Captain Makarov, (fnu), were subordinate to Colonel Postnikov. The officers of the construction staff were yellow-bordered red epaulets and red ribbons on their caps. (1)  The following is a description of the jet fighters at the field:  Cockpit canopy slide back; nosewheel extends rearward and not forward as previously reported; two cannons one above the other on left side of nose when observed from the front, two machine guns on right side, one a little to the rear; The brocchi piece of weapons with live ammunition is marked by red flags when aircraft are parked. Planes that are refueled are fitted with
2.	Soviet construction offices located in Karlshorst (N 53/Z 94) and Werder (N 53/Z 63).  The construction staff in Neuruppin including Lieutenant Colonel Vinegradov, (fnu), and technical officer Captain Makarov, (fnu), were subordinate to Colonel Postnikov. The officers of the construction staff were yellow-bordered red epaulets and red ribbons on their caps. (1)  The following is a description of the jet fighters at the field:  Cockpit canopy slide back; nesewheel extends rearward and not forward as previously reported; two cannons one above the other on left side of nose when observed from the front, two machine guns on right side, one a little to the rear; The broccht piece of weapons with live ammunition is marked by red flags when aircraft are parked. Planes that are refueled are fitted with a flag on the nose, the flags being removed prior to take off; aircraft were
2.	Soviet construction offices located in Karlshorst (N 53/Z 94) and Werder (N 53/Z 63).  The construction staff in Neuruppin including Lieutenant Colonel Vinogradov, (fnu), and technical officer Captain Makarov, (fnu), were subordinate to Colonel Postnikov. The officers of the construction staff were yellow-bordered red epaulets and red ribbons on their caps. (1)  The following is a description of the jet fighters at the field:  Cockpit canopy slide back; nosewheel extends rearward and not forward as previously reported; two cannons one above the other on left side of nose when observed from the front, two machine guns on right side, one a little to the rear; The brocchi piece of weapons with live ammunition is marked by red flags when aircraft are parked. Planes that are refueled are fitted with
	Soviet construction offices located in Karlshorst (E 53/Z 94) and Werder (E 53/Z 63).  The construction staff in Meuruppin including Lieutenant Colonel Vinegradov, (fnu), and technical officer Captain Makarov, (fnu), were subordinate to Colonel Postnikov. The officers of the construction staff were yellow-bordered red epaulets and red ribbons on their caps. (1)  The following is a description of the jet fighters at the field:  Cockpit canopy slide back; nosewheel extends rearward and not forward as previously reported; two camens one above the other on left side of nose when observed from the front, two machine guns on right side, one a little to the rear; The broach piece of weapons with live ammunition is marked by red flags when aircraft are parked. Planes that are refueled are fitted with a flag on the nose, the flags being removed prior to take off; aircraft were  Soviet star is painted on the fuselage and also on the rudder assembly; a flap, was on the rear part of the fuselage, and was closed prior to take off. (2)  Two single-engine, highwing planes with rigid landing gear, three single-engine
	Soviet construction offices located in Karlshorst (# 53/2 9h) and Werder (# 53/2 63).  The construction staff in Meuruppin including Lieutenant Colonel Vinogradov, (fnu), and technical officer Captain Makarov, (fnu), were subordinate to Colonel Postnikov. The officers of the construction staff were yellow-bordered rod epaulets and red ribbons on their caps. (1)  The following is a description of the jet fighters at the field:  Cockpit canopy slids back; nosewheel extends rearward and not forward as previously reported; two camons one above the other on left side of nose when observed from the front, two machine guns on right side, one a little to the rear; The broacht place of weapons with live ammunition is marked by red flags when aircraft are parked. Planes that are refueled are fitted with a flag on the nose, the flags being removed prior to take off; aircraft were  Soviet star is painted on the fuselage and also on the rudder assembly; a flap, was on the rear part of the fuselage, and was closed prior to take off. (2)  Two single-engine, highwing planes with rigid landing gear, three single-engine aircraft, about 12 PO-2s, and 18 silver-gray jet fighters were parked on the field up to 13 Earch. (3) There was intensive flying day and night. Formation
	Soviet construction offices located in Karlshorst (E 53/Z 94) and Werder (E 53/Z 63).  The construction staff in Meuruppin including Lieutenant Colonel Vinogradov, (fnu), and technical officer Captain Makarov, (fnu), were subordinate to Colonel Postnikov. The officers of the construction staff were yellow-bordered red epaulets and red ribbons on their caps. (1)  The following is a description of the jet fighters at the field:  Cockpit canopy slide back; nosewheel extends rearward and not forward as proviously reported; two camnons one above the other on left side of nose when observed from the front, two machine guns on right side, one a little to the rear; The broach piece of weapons with live annunition is marked by red flags when aircraft are parked. Planes that are refueled are fitted with a flag on the nose, the flags being removed prior to take off; aircraft were  Soviet star is painted on the fuselage and also on the rudder assembly; a flap, was on the rear part of the fuselage, and was closed prior to take off. (2)  Two single-engine, hip-wing planes with rigid landing gear, three single-engine aircraft, about 12 Po-2s, and 18 silver-gray jet fighters were parked on the field up to 13 Earch. (3) There was intensive flying day and night. Formation flying by four jet aircraft and take-offs by two jet planes were practiced during
	Soviet construction offices located in Karlshorst (2 53/2 94) and Werder (2 53/2 63).  The construction staff in Meuruppin including Lieutenant Colonel Vinogradov, (fnu), and technical officer Captain Makarov, (fnu), were subordinate to Colonel Postnikov. The officers of the construction staff were yellow-bordered rod epaulets and red ribbons on their caps. (1)  The following is a description of the jet fighters at the field:  Cockpit canopy slide back; nesewheel extends rearward and not forward as proviously reported; two camnons one above the other on left side of nose when observed from the front, two machine guns on right side, one a little to the rear; The brooch piece of weapons with live ammunition is marked by red flags when aircraft are parked. Planes that are refueled are fitted with a flag on the nose, the flags being removed prior to take off; aircraft were  Soviet star is painted on the fuselage and also on the rudder assembly; a flap, was on the rear part of the fuselage, and was closed prior to take off. (2)  Two single-engine, highwing planes with rigid landing gear, three single-engine aircraft, about 12 PO-2s, and 18 silver-gray jet fighters were parked on the field up to 13 Earch. (3) There was intensive flying day and night. Formation flying by four jet aircraft and take-offs by two jet planes were practiced during the daytine. The average flying time was about 15 to 20 minutes. The jet
	Soviet construction offices located in Karlshorst (E 53/2 9h) and Werder (E 53/2 63).  The construction staff in Meuruppin including Lieutenant Colonel Vinogradov, (fmu), and technical officer Captain Makarov, (fmu), were subordinate to Colonel Postnikov. The officers of the construction staff were yellow-bordered rod epaulets and red ribbons on their caps. (1)  The following is a description of the jet fighters at the field:  Cockpit canopy slids back; nosewheel extends rearward and not forward as previously reported; two camons one above the other on left side of nose when observed from the front, two machine guns on right side, one a little to the rear; The breecht piece of weapons with live amaunition is marked by red flags when aircraft are parked. Planes that are refueled are fitted with a flag on the nose, the flags being removed prior to take off; aircraft were  Soviet star is painted on the fuschage and also on the rudder assembly; a flap, was on the rear part of the fuschage, and was closed prior to take off; (2)  Two single-engine, highwing planes with rigid landing gear, times single-engine aircraft, about 12 PO-2s, and 18 silver-gray jet fighters were parked on the field up to 13 March. (3) There was intensive flying day and night. Forcation flying by four jet aircraft and take-offs by two jet planes were practiced during the daytime. The average flying time was about 15 to 20 minutes. The jet fighters did not fly during the night. Twin-engine aircraft which were not stationed at the field were repeatedly seen flying over the airfield at night.
	Soviet construction offices located in Karlshorst (E 53/2 9h) and Werder (E 53/2 63).  The construction staff in Meuruppin including Lieutenant Colonel Vinogradov, (fnu), and technical officer Captain Makarov, (fnu), were subordinate to Colonel Postnikov. The officers of the construction staff were yellow-bordered red epaulets and red ribbons on their caps. (1)  The following is a description of the jet fighters at the field:  Cockpit canopy slids back; nosewheel extends rearward and not forward as previously reported; two camons one above the other on left side of nose when observed from the front, two machine guns on right side, one a little to the rear; The broach piece of weapons with live ammunition is marked by red flags when aircraft are parked. Planes that are refueled are fitted with a flag on the nose, the flags being removed prior to take off; aircraft were  Soviet star is painted on the fuselage and also on the rudder assembly; a flap, was on the rear part of the fuselage, and was closed prior to take off. (2)  Two single-engine, highwing planes with rigid landing gear, three single-engine aircraft, about 12 Po-2s, and 18 silver-gray jet fighters were parked on the field up to 13 March. (3) There was intensive flying day and night. Formation flying by four jet aircraft and take-offs by two jet planes were practiced during the daytime. The average flying time was about 15 to 20 minutes. The jet fighters did not fly during the night. Twin-engine aircraft which were not
	Soviet construction offices located in Karlshorst (E 53/2 9h) and Werder (E 53/2 63).  The construction staff in Meuruppin including Lieutenant Colonel Vinogradov, (fmu), and technical officer Captain Makarov, (fmu), were subordinate to Colonel Postnikov. The officers of the construction staff were yellow-bordered rod epaulets and red ribbons on their caps. (1)  The following is a description of the jet fighters at the field:  Cockpit canopy slids back; nosewheel extends rearward and not forward as previously reported; two camons one above the other on left side of nose when observed from the front, two machine guns on right side, one a little to the rear; The breecht piece of weapons with live amaunition is marked by red flags when aircraft are parked. Planes that are refueled are fitted with a flag on the nose, the flags being removed prior to take off; aircraft were  Soviet star is painted on the fuschage and also on the rudder assembly; a flap, was on the rear part of the fuschage, and was closed prior to take off; (2)  Two single-engine, highwing planes with rigid landing gear, times single-engine aircraft, about 12 PO-2s, and 18 silver-gray jet fighters were parked on the field up to 13 March. (3) There was intensive flying day and night. Forcation flying by four jet aircraft and take-offs by two jet planes were practiced during the daytime. The average flying time was about 15 to 20 minutes. The jet fighters did not fly during the night. Twin-engine aircraft which were not stationed at the field were repeatedly seen flying over the airfield at night.
	Soviet construction offices located in Karlshorst (E 53/Z 94) and Werder (E 53/Z 63).  The construction staff in Neuruppin including Lieutenant Colonel Vinogradov, (fnu), and technical officer Captain Makarov, (fnu), were subordinate to Colonel Postnikov. The officers of the construction staff were yellow-bordered rod opaulets and red ribbons on their caps. (1)  The following is a description of the jet fighters at the field:  Cockpit canopy slids back; nosewheel extends rearward and not forward as proviously reported; two camons one above the other on left side of nose when observed from the front, two machine guns on right side, one a little to the rear; The broech piece of weapons with live annunition is marked by red flags when aircraft are parked. Planes that are refused are fitted with a flag on the nose, the flags being removed prior to take off; aircraft were  Soviet star is painted on the fuselage and also on the rudder assembly; a flap, was on the rear part of the fuselage, and was closed prior to take off; (2)  Two single-engine, highwing planes with rigid landing gear, three single-engine aircraft, about 12 Po-2s, and 18 sllver-gray jet fighters were parked on the field up to 13 March. (3) There was intensive flying ay and night. Formation flying by four jet aircraft and take-offs by two jet planes were practiced during the daytime. The average flying the was about 15 to 20 minutes. The jet fighters did not fly during the night. Twin-engine aircraft which were not stationed at the field were repeatedly seen flying over the airfield at night. Luring the first week of Earch, a formation of 16 jet fighters landed at the
	Soviet construction offices located in Karlshorst (E 53/2 9h) and Werder (E 53/2 63).  The construction staff in Meuruppin including Lieutenant Colonel Vinogradov, (fnu), and technical officer Captain Makarov, (fnu), were subordinate to Colonel Postnikov. The officers of the construction staff were yellow-bordered rod opaulets and red ribbons on their caps. (1)  The fellowing is a description of the jet fighters at the field:  Cockpit canopy slide back; nosewheel extends rearward and not forward as previously reported; two camons one above the other on left side of nose when observed from the front, two machine guns on right sides, one a little to the rear; The broech piece of weapons with live amunition is marked by red flags when aircraft are parked. Planes that are refueled are fitted with a flag on the nose, the flags being removed prior to take off; aircraft were  Soviet star is painted on the fuselage and also on the rudder assembly; a flap, was on the rear part of the fuselage, and was closed prior to take off; (2)  Two single-engine, hiphwing planes with rigid landing gear, three single-engine aircraft, about 12 PO-2s, and 18 silver-gray jet fighters were parked on the field up to 13 Earch. (3) There was intensive flying day and night. Formation flying by four jet aircraft and take-offs by two jet planes were practiced during the daytime. The average flying time was about 15 to 20 minutes. The jet fighters did not fly during the night. Twin-engine aircraft which were not stationed at the field were repeatedly seen flying aircraft which were not stationed at the field were repeatedly seen flying aircraft which were not stationed at the field were repeatedly seen flying aircraft which were not stationed at the field were repeatedly seen flying aircraft which were not stationed at the field were not seen flying over the airfield at night.
	Soviet construction offices located in Karlshorst (E 53/Z 94) and Werder (E 53/Z 63).  The construction staff in Neuruppin including Lieutenant Colonel Vinogradov, (fnu), and technical officer Captain Makarov, (fnu), were subordinate to Colonel Postnikov. The officers of the construction staff were yellow-bordered rod opaulets and red ribbons on their caps. (1)  The following is a description of the jet fighters at the field:  Cockpit canopy slids back; nosewheel extends rearward and not forward as proviously reported; two camons one above the other on left side of nose when observed from the front, two machine guns on right side, one a little to the rear; The broech piece of weapons with live annunition is marked by red flags when aircraft are parked. Planes that are refused are fitted with a flag on the nose, the flags being removed prior to take off; aircraft were  Soviet star is painted on the fuselage and also on the rudder assembly; a flap, was on the rear part of the fuselage, and was closed prior to take off; (2)  Two single-engine, highwing planes with rigid landing gear, three single-engine aircraft, about 12 Po-2s, and 18 sllver-gray jet fighters were parked on the field up to 13 March. (3) There was intensive flying ay and night. Formation flying by four jet aircraft and take-offs by two jet planes were practiced during the daytime. The average flying the was about 15 to 20 minutes. The jet fighters did not fly during the night. Twin-engine aircraft which were not stationed at the field were repeatedly seen flying over the airfield at night. Luring the first week of Earch, a formation of 16 jet fighters landed at the



25X1

- The radio installation conisted of a wooden hut about 2.5 meters square and four masts. An antenna lead from each masthead to the wooden hut. (5) Twenty meters northwest of this hut was another wooden hut of the same size. This hut had a four-circuit overhead line which came from the officers' mess and extended along the Klappgraben. A third wooden hut, 10 meters long and 3 meters wide, was located 20 meters northwest of the second hut. There was a generator in this hut and a gasoline engine which was heard running.
- 5. The fuel dump next to the officers' mess had a total capacity of about 400,000 kg. It consisted of three semi-underground containers, which came from former German air force installations, each container having a capacity of 50,000 kg; eight semi-underground containers each with a capacity of 15,000 kg; and 18 to 20 underground containers, dug-in in groups of three. The fuel dump was filled to about two thirds of its capacity. Fuel arrived in railroad tank cars. Dogs, chained on leashes about 30 to 50 meters long, guarded the fuel dump. Leashes for the watchdogs were also seen fastened between the telephone polesyalong the Klappgraben.
- The rotary searchlight was removed from the repair hangar and mounted on a truck. The graves at the cemetery 50 meters from Wittstock Allee were leveled off for the construction of a wooden

7.	

Comments.

25X1

25X1

(1) Colonel Vinogradov, (flu), was previously reported from Neuruppin as

chief of the airfield construction. 25X1

According to previous observations, the nose wheel of the MIG-15 is retracted to the rear. No swept-back wing jet aircraft type is known which retracts its nose wheel forward. The armament reported differs from the MIG-15 type previously known which is equipped with two machine guns and one cannon. Red flags were often reported to be fitted on the nose of aircraft. Their purpose is not known. Since such flags have been observed almost always on aircraft, not covered with tarpaulins, the reason[

is believed credible. 25X1 25X1

The aircraft are assigned to a fighter regiment transferred from Oranien-25X1 burg to Neuruppin. A total of 18 different aircraft

observed at Neuruppin. The large number of PO-2s cannot be explained. (4) It has not been determined to which fighter regiment

The description indicates that the radio installation is perhaps a transmitting and receiving installation, but not an Adcock DF.

25X1